Work Order	II	96	5717
Monday, February	11,	2013	4:24

	er ID 96717 ary 11, 2013 4:24:	55 PM		*967	÷			Page 1			
Item ID: Revision ID:	D3849-043		A	Accept	*N900	040	100)* Se	etup Start	IA.	S1*
Item Name:	Aft Wearplate Asse	mbly, STD Gear							Stop	*N:	32 *
Start Date:	1/31/2013 Sta	art Qty: 2.00	*2*		Cust Item II	D:					
Required Date:	2/1/2013 Re	q'd Qty: 2.00	*2*		Customer:	CU-D	AR001				
Reference:	RMA RA111416	- Retur	27								
Approvals:	Process Plan:	MF	Date: \3-2-11	Tooling:	Da	ite:		R	un Star	"171	₹1*
	QC:		Date:	SPC (Y/N):	Da			Stop	*NI	₹2*	
Sequence ID/ Work Center II		eration cription		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision	Nbr									
D3849	D										
*100 *100* QC		Memo		0.00 0.00 OAS	1						
Quality Control		INSPECT R PARTS ARI	A 111416 D 3849-043 X 2 I E SCRAP	B#52402 16	17/2/12						
110				0.00							
110 Small Fab Small Fab		Mem o SCRAP PAI	RTS	0.00				_2	ø	Ac	13.02.A
120	QC	21- Final Inspection -	Work Order Release	0.00				1		1	10
120 QC		Memo		0.00					3/2	130	1
Quality Control										. <	13-02

ML 5

Picklist Print

Monday, February 11, 2013 4:24:55 PM

Page 1

Work Order ID:

96717

Parent Item:

D3849-043

Parent Item Name:

Aft Wearplate Assembly, STD Gear

Start Date: 1/31/2013

Required Date: 2/1/2013

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP RevA: New issue DD verified by:EC DWG REV.D DD VERF:JLM

IPP Rev:B 12.09.11 AS PER

	DWG KEV.D DD	V LICI .JLIVI											
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3849-043		Manufactured	No			··	Each	0.0000		2			
Aft Wearnlate Accombly	CTD Goor									-			

Aft Wearplate Assembly, STD Gear

2 x * 5 2402